



STIHL






































**Maintenance in everyday
operations
f**

Preventative Maintenance



- Importance of preventative maintenance
- Why should we be doing this
- How do we know when it should be done
- Who should do these maintenance intervals
- Maintenance costs me too much money



	FS 161 *2* (CAGE) ✂ FS 161-L Freischneider	 Maintenance Check condition of AV elements	2 days ago	47:20 h	--- h	372545934	 Test Machines for Product Laun
	FS 161 *3* (CAGE) ✂ FS 161-L Freischneider	 Maintenance Replace pickup body (filter) in fuel tank	2 months ago	195:32 h	--- h	372771713	 Test Machines for Product Laun
	FS 235 *1* (CAGE) ✂ FS 235 Brushcutter	 Marketing damage Gearbox broken waiting for new from marketing	3 days ago	145:02 h	--- h	831967861	 Petrol Brushcutters
	FS 235 *2* (CAGE) ✂ FS 235 Brushcutter		3 days ago	17:14 h	--- h	831967870	 Petrol Brushcutters
	FS 260 (CAGE) ✂ FS 260 Freischneider		3 days ago	00:00 h	--- h	189971637	 Petrol Brushcutters
	FS 291 *1* (BURGESS VCC) ✂ FS 291-L Freischneider	 Maintenance Complete visual inspection	2 months ago	62:09 h	--- h	372705093	 Test Machines for Product Laun
	FS 291 *2* (SOLD) ✂ FS 291-L Freischneider	 Maintenance Replace pickup body (filter) in fuel tank	2 months ago	05:23 h	--- h	372705090	 Test Machines for Product Laun
	FS 291 *4* (CAGE) ✂ FS 291-L Freischneider	 Maintenance Complete visual inspection	3 days ago	193:10 h	--- h	372705049	 Test Machines for Product Laun
	FS 291 *5* (Ryan Jenkins) ✂ FS 291-L Freischneider	 Maintenance Replace pickup body (filter) in fuel tank	2 months ago	09:25 h	--- h	372705127	 Test Machines for Product Laun
	FS 460 *1* CLEARING SAW (CAGE) ✂ FS 460 C-EM K Clearing Saw	 Maintenance Check condition of AV elements	3 days ago	77:23 h	--- h	193151004	 Petrol Brushcutters
	FS 460 *2* CLEARING SAW (CAGE) ✂ FS 460 C-EM K Clearing Saw	 Maintenance Complete visual inspection	1 day ago	53:01 h	--- h	193151042	 Petrol Brushcutters
	FS 460 *3* NORMAL (CAGE) ✂ FS 460-L Freischneider	 Maintenance Complete visual inspection	2 days ago	00:27 h	--- h	372724373	 Petrol Brushcutters
	FSA 135 FSA 135 Akku-Motorsense					540131454	
	FSA 200 R (CAGE) ✂ FSA 200.0 R Akku-Motorsense		2 days ago	01:30 h	--- h	447071435	 Professional Battery Machines





Test the new version of STIHL connected Portal >



STIHL apps



Products

Fleet management

Organization

Products / MS 462 (CAGE)

MS 462 (CAGE)

Overview Events Usage Statistics Smart Connector Details

LOCATION

5 Bush Shrike Close, Montrose, Pietermaritzburg, 3201, South Africa

Navigate

MS 462 CHAINSAW

MS 462 (CAGE)

Add teams

Check condition



Last data synchronization 2 days ago

Runtime today --- h

Total runtime 19:35 h

Keywords

Add keywords



Upload JPG, PNG, GIF up to 7 MB per image



EVENTS

Show all events

Create Maintenance

Contact Dealer



Upload JPG, PNG, GIF up to 7 MB per image

EVENTS

Show all events + Create Maintenance Contact Dealer

Current (3) Upcoming (18) Completed

	Maintenance	Check operation of chain lubrication	2 months ago
	Maintenance	Check chain braking system	2 months ago
	Maintenance	Check operation of chain brake	4 months ago

USAGE STATISTICS

Latest change ↻ 2 days ago

No data available

RUNTIME TODAY

19:35_h

TOTAL RUNTIME

RUNTIME HISTORY

Interval





Upload JPG, PNG, GIF up to 7 MB per image

EVENTS

Show all events Create Maintenance Contact Dealer

Current (3)	Upcoming (18)	Completed
	Maintenance Deburr the guide bar due in 05:24 h	
	Maintenance Check condition of chain catcher due in 05:24 h	
	Maintenance Check condition of air filter due in 05:24 h	
	Maintenance Check condition of saw chain due in 05:24 h	
	Maintenance Clean cylinder fins due in 30:24 h	
	Maintenance Clean air inlet on fan housing due in 30:24 h	
	Maintenance Check condition of guide bar due in 30:24 h	

USAGE STATISTICS


Latest change 2 days ago

No data available RUNTIME TODAY	19:35 h TOTAL RUNTIME
------------------------------------	--------------------------

RUNTIME HISTORY

Interval





LOCATION

5 Bush Shrike Close, Montrose, Pietermaritzburg, 3201, South Africa

Navigate



FS 235 BRUSHCUTTER

FS 235 *1* (CAGE)

Petrol Brushcutters

Non-operational

Last data synchronization 3 days ago

Runtime today --- h

Total runtime 145:02 h

Keywords

Add keywords



Upload JPG, PNG, GIF up to 7 MB per image



EVENTS

Show all events

Create Maintenance

Contact Dealer

SMART CONNECTOR

✎ Connector linked ✕ Disconnect

Coin cell battery status ⓘ	🔋 Connector battery OK
Operating time	145:02 h
Connector ID	001343F85F53
Installation	2023/04/26
Software information	01.00
Hardware information	00.80

DETAILS

Serial number	831967861	Dealer Add a new dealer
Drive	Petrol	Please select a dealer
Manufacturer	STIHL	
Category	Clearing saws	
Article number	41512000018	
Date of purchase	Add date of purchase	
Warranty end date	Add warranty end date	
Notes		
With harness		

Documents

📁

Drag & drop files here or

[Browse files](#)

Upload DOC, DOCX, GIF, JPEG, PDF, PNG, TIFF files up to 7MB

🗑 Remove product



USAGE STATISTICS


Latest change  3 days ago




RUNTIME HISTORY

Interval

Months 




Runtime per month
Average runtime per month 


MONTHS | 2024



SMART CONNECTOR

 Connector linked  Disconnect

Coin cell battery status 

 Connector battery OK



STIHL



STIHL

**THANK
YOU**

